

Model 765-16B Barometric Standard -- Quick Reference Menu

Barometer

P Tendency

Functions

Alt. Setting

Field Pressure

Station P

Sea-Level P

P Altitude

Dens. Altitude

Q Signals

QNH

QFE

Settings

Field Elev.

Sensor Elev.

Station Elev.

5-min. Temp

12-hour Temp.

P Reduc. Const.

Display

Line 1 Display

Pressure

Avg. Pressure

Line 2 Display

Cur. Tare Value

P Rate

P Trend

P Scatter

Min Max P

Bar Graph

Sensor Temp

Stored Text

External Text

Disable

Backlight

Enable

Disable

Timeout Period

Decimal Digits

Contrast

Data Logging

Start Logging

Immediate

Programmed

View Data

Delete Data

Avail. Memory

Burst Mode

Disable

Enable

Wraparound

Enable

Disable



System

Sampling Time

Reset Min/Max P

Battery Charge

Alarm Setpoints

Lower Setpoint

Upper Setpoint

Num. P Points

Communication

Unit ID

Baud Rate

Set Date/Time

Date Format

MM/DD/YY

DD/MM/YY

Time Format

12 HR

24 HR

Password

Version